



COMPANIA DE APA TARGOVISTE-DAMBOVITA



Bd. I.C.Bratianu, nr.50, cod postal 130055, Targoviste, jud.Dambovita

Tel. +40245.614403 0800800168 (tel.verde) Fax. +40245.611774
www.catd.ro secretariat@catd.ro

REZULTATELE MONITORIZARII CALITATII APEI UZATE SEMESTRUL III 2024

Indicatori chimici monitorizati la IESIREA din Statia de Epurare **PARC INDUSTRIAL PRIBOIU** – NOIEMBRIE 2024

Tip proba-apa uzata

| Indicator analizat | Punct de prelevare | U.M. | Val. inregistrata | Val. max. | Val. min. | Nr. mas. | Nr. Depasiri CMA sau VL | CMA /VL conf. AM nr.97/05.07.2023 AGA nr. 18/26.03.2024 | Metoda de analiza (STAS, ISO) |
|--------------------|--------------------|------------|-------------------|-----------|-----------|----------|-------------------------|--|-------------------------------|
| pH | Iesire statie | unitati ph | 7,4 | - | - | 1 | 0 | 6.5-8.5 | SR ISO 10523/2012 |
| MTS | | mg/l | 5,8 | - | - | 1 | 0 | 60 | SR EN 872/2005 |
| CBO ₅ | | mg/l | 3 | - | - | 1 | 0 | 25 | SR EN ISO 5815-1:2020 |
| CCO-Cr | | mg/l | <30 | - | - | 1 | 0 | 125 | SR ISO 6060/96 |
| SE | | mg/l | <20 | - | - | 1 | 0 | 20 | SR 7587/96 |
| Reziduu fix | | mg/l | 192 | - | - | 1 | 0 | 2000 | STAS 9187/84 |
| Detergenti | | mg/l | <0,1 | - | - | 1 | 0 | 0,5 | SR EN 903/2003 |
| Fosfor total | | mg/l | 0,08 | - | - | 1 | 1 | 2 | SR EN ISO 6878/2005 |
| Azot total | | mg/l | 1,5 | - | - | 1 | 1 | 15 | SR EN ISO 20236:2021 |
| Amoniu | | mg/l | 0,13 | - | - | 1 | 0 | 3 | SR ISO 7150-1/2001 |
| Azotati | | mg/l | 3,7 | - | - | 1 | 1 | 37 | SR EN ISO 7890-3:2020 |
| Cloruri | | mg/l | 6,2 | - | - | 1 | 0 | 500 | SR EN ISO 10304-1/2009 |

CMA - concentratie maxima admisa sau VL – valoare limita

U.M. - unitate de masura

Conform Raport de incercare – Nr.1800/28.11.2024